

TRUSTEES REPORT: September Church Council meeting 2015

Work has started on ceiling of the northwest bell tower. Completion of major work by Sept. 6th, depends on how well, fast materials dry. New light fixture and other related work to be wrapped up in the next couple of weeks.

As you have noticed, the asphalt patch work and white "x" marks on the public sidewalk around the property; asphalt is a temporary repair, replacement of sidewalk sections have been included in the city's replacement program for next year. The old driveway approach and curb are still pending a city inspection for replacement.

Trustees are starting an investigation on replacing the current telephone system with one from this century. Details pending.

Replacement of concrete landing and curb by eastside entry to building may happen this year. Details pending.

All major building inspection should have been completed by September 1st. Need to find out if stage door inspection has occurred.

Trustee President and Vice President have signed architect agreement for the necessary working drawings needed for a building permit.

The junior executive trustee has completed pothole patching on parking lot. Materials cost \$124.00. Labor rate: PRICELESS. See picture in last month's e-tidings.

Sanctuary light bulb replacement scheduled for October 3, 2015 at 8:30am. You do not have to be a trustee to participate in this adventure, all welcome.

Respectfully submitted,

Jim McCloud, President of Trustees