

Trustees Report

Church Council November 2015

1. Contract signed for snow removal
2. Downspout work completed on NW tower. Install access hatch & trim and paint.
3. Sanctuary light bulb project completed. LED dimmable bulbs installed.
4. Sanctuary skylight T12 bulbs installed
5. Lawn at both parsonages has been aerated.
6. Nursery room window insulated panel has been installed.
7. Process of getting new electronic board installed in outdoor sign, have board waiting for installation person from Stewart Signs.
8. Trustees to vote on tow company signs for parking lot this month.
9. Boiler company contacted, boiler cleaned at fired up. May be last year possibly two. Lower tubes (1 or 2) have drip leaks. Can not repair, too expensive. Boiler had major work done in 2010, repair and or remove lower tubes and clean. 2012 upper tubes replaced, new auto fill valve and correctly wired brain box. Boiler begging for retirement, installed in 1952.

That is all as of 11-02-15.

Respectfully submitted,

Jim McCloud, POT